

CODA

C O D A A U D I O



New Features
- LINUS Control v2.9.1 -





- 1. *New Features* 3
 - 1.1. Firmware update for LINUS6.4.....3
 - 1.2. Speaker update for LINUS6.4.....3
 - 1.3. Minor updates3



1. New Features

1.1. Firmware update for LINUS6.4

This Firmware implements

- Updated limiter performance
- Prevent processor freeze at quick reboot
- "DC Error" shown in display when there is a fault condition
- Highpass at 10Hz to avoid triggering DC Protect
- AES clock lock improvements

1.2. Speaker update for LINUS6.4

N-RAY, and KTV Soundbar speakers are now available for the LINUS6.4

1.3. New Speaker Presets

APS-Pro D/S added to preset library

1.4. Minor updates

Bridged Icon at loudspeaker banner is showing if a bridged preset is selected for LINUS6.4



**IMPORTANT**

Due to essential component update on the LINUS14 / LINUS14D and LINUS12C amplifiers, no backwards compatibility to firmware versions older than V x.69 is possible.

Affected amplifiers starting with this serial number:

LINUS14/ D: 19030863

LINUS12C: 21090214

Please refer do document "LINUS Control v2.9.1 Known Issues" for further information

Product	Firmware Version
LINUS6.4	V2.5
LINUS 14 / LINUS14-D	V3.70
LINUS12C	V3.71
LINUS10	V2.70
LINUS10-C	V5.70
LINUS5-C	V5.70
LINUS CON	V1.70